# SOUTH PRODUCTION NOTES

December 25, 2014 3-11 Shift Notes

BASF EMPLOYEES
64 Last Recordable
544 Last Lost Time

Be sure to check weigh all bags off of the calciners and fill out the log sheet downstairs by the scale and Attach "Packaged By" label with your initials.

All: check your CBT's to be sure they are finished up to the end of the Year

## #1 MED / AL 4126 1/16th:

Wednesday afternoon update...will run 5 more batches starting Thursday midnight shift, and need to get calcining by Thursday. Need to complete lot 45 (20 bags) on calciner

Midnight shift: running need 7-8 more batches

Day shift: holding batches made

Afternoon shift:

## #1 RC /AL 4126 1/16th:

Wednesday afternoon update...will have Trimer acid washed Thursday morning and try to have ready to feed calciner on Thursday Midnight Shift: hold Trimer being cleaned out tomorrow Day shift: Trimer cleaning, hoping to start Calciner on afternoon shift, Gavalek will finish on afternoon shift and start Trimer back up. Afternoon shift:

Exhaust to F1 until we are feeding again, then to Trimer

## **#2 MED line / Cu-0860:**

Wednesday afternoon update...World Metals 3818 material for powder room purged out of powder room hopper. Will restart line and run several batches Wednesday afternoon, then hold for dried and calcined results from lab. Be sure to use wet mix on every batch.

Midnight shift: holding

Day Shift: Manually sent powder for first batch. Running with no issues. Should have made 3 batches by the end of the shift. Need to calcine material.

Afternoon Shift:

# #2 RC/ Cu 0860:

Bladder on bag off station should be working now. Still need to feed bags on 1st

floor (Bodmann will advise)

Midnight shift: running

Day Shift: Ready to run, should be started by the end of the shift

**Afternoon Shift:** 

#### **Exhaust to F1**

## #3 MED/ D-1780:

Running. Door seals have been replaced.

Midnight shift: Continued

Day Shift: running Afternoon Shift:

## #3 RC / D 1780:

Continued. Screener skimmed over, installed Cleaning kit. Per Bodmann take oversized line to a drum for approx. 2 hr to try and get rid of the little balls of material that are coating the Screener. Label as oversized and put in red zone.

Midnight shift: Continue Day shift: continued Afternoon Shift:

#### **Exhaust to CTO**

## #4 RC / 5202:

Continued to feed. Have been running with a discharge rate around 400 without any leaks. Many attempts have been made to run above 600, but the feed end has leaked every time.

Midnight shift: continue feeding, Last bag hanging, Be sure to close slide gate when hopper MT

Day Shift: done with feed. Shutting down Calciner

**Afternoon Shift: Continue** 

## **Exhaust to Trimer**

## #5 RC / Cu-3818:

Running 3818 again. Make sure temps are correct and follow MOD. Make sure we are keeping the feed hopper filled, it is affecting the SA for this product because we are not getting consistent feed rates.

Midnight Shift: feeding

Day shift:

Afternoon shift: feeding

#### **Exhaust to 5A DC**

## #6 RC & Dryer / D-0257

Use Auto Sampler for bags, and get additional grab sample for each bag.

Midnight shift: running

Day Shift: Continued, no labels for the rest of lot 2, use copy labels and put bags by #1 calciner, until Hebb can print the correct labels. Do not load on truck with incorrect labels.

Afternoon shift:

# **Exhaust to Sly Scrubber**

## 6 Tank /D-5253 empty

Continue. Drain looked at by Schirmer and Lucas- not fixed yet

Midnight Shift: no activity
Day Shift: No activity
Afternoon shift: NA

## New Pfaudler / D 5253 done

Pfaudler glass was inspected Friday.

Midnight Shift: No change.

Day Shift: No activity Afternoon Shift: NA

## 7 Tank AMT, KLP solution next?

Hold Eliott advised that radar gauge on tank is not working. Will need repaired.

Midnight Shift: NA Day Shift: NA

Afternoon shift: NA

## Old Pfaudler / D-0257:

NOTE: Be sure to sample drainage from each batch made on east pfaudler for

D 0257 batches. Water pick up for lot 16 is .82, and for lot 17 is .80.

Midnight Shift: Made batch Day Shift: hold for space

Afternoon shift:

# National Dryer:

Schirmer finished bead blasting.

Midnight Shift: NA
Day shift: NA

Afternoon Shift: NA

# PK Blender/X 1000 repacks:

PK Clean and ready for repacks

Midnight Shift: holding for modifications to pk

Day shift: holding

Afternoon shift: Hold-MOC scheduled for repack changes on Friday

## Abbe Blender / 5206 Done

Done for a while. Area Cleaned

Midnight shift: NA
Day shift: NA
Afternoon shift: NA

## **Tower 3/ Cu 0860:**

Running, instructed to produce through batch 332-verify alcohol is onsite

before loading 333. Midnight Shift: holding

Day shift: down holding, reload on Saturday morning 11-7 shift

Afternoon shift:

## Tower 6 / Pd 1930:

Pd 1930 material here for repacking...schedule as needed before each tower load. Reuse drums, if drums are in good condition, black out labels with spray paint and put new label on drum. 30 drum tower loads.

Midnight Shift: Holding until Friday. Unloaded and drums leveled, they are in

the poll barn

Day shift: down, holding for more Pd.

Afternoon shift:

## North Screener / Cu-0860:

Change to Cu-0860. Keep running WOW for leaking Pump

Midnight shift: hold

Day shift: ran 1<sup>st</sup> ½ of shift.

Afternoon shift:

## **South Screener / Cu-0860:**

Change to Cu-0860. Keep running, WOW for leaking Pump

Midnight shift: hold

Day shift: ran 1<sup>st</sup> ½ of shift

**Afternoon Shift:** 

# #2662 (west) Pill Machine / Al-3915 T 5/32:

Running, when able.

Midnight shift: continued

Day Shift: running Afternoon shift:

# #2664 (east) Pill Machine / Al-3915 T 5/32:

Running, when able.

Midnight shift: continued

Day Shift: Running Afternoon shift:

## TK #2 / V 2046/V 2010:

Down for now. Will need to be switched to V-2010 Saggers...will discuss next

week

Midnight shift: Down Day Shift: Down

**Afternoon shift: Down** 

## TK #4 / Cu 2508 next:

Lighting kiln Monday afternoon, Bring Kiln up to temps change out saggers to 2508 Saggers. Clean out existing Saggers and palletize 0540 Saggers for future run.

Midnight shift: not able to run, car would not advance

Day Shift: Running changing out saggers, disassemble and clean Screener.

Change out drums. Call North end for projected start time so they can

schedule the blender.

Afternoon shift:

## Harrop Kiln / Al 3920:

Al 3920 - 90 min Cart- operator must keep area cleaned

Midnight shift: Continue Day Shift: Continue

Afternoon shift: Continue

## **Building 27 Belt Filter / 5020:**

Cu-5020.

Midnight shift: Run on midnights, will run on days.

Day shift: Ran, had issues with belt kicking out and dryer. Maintenance looked at recycle pump on 107 and it appears that the lines are getting clogged by the material soda ash and britesorb solution and causing the pump to kick out on low limit because it runs dry, do not continue to reset the pump if you have this issue, running it dry will damage the pump. Will need to run on midnights to get rid of batch, and we should be able to run on day shift tomorrow.

#### **Afternoon Shift:**

#### **Priorities:**

Priorities 1 through 12 are basically all the same priority, should be considered urgent and will require call outs for maint issues and/or processing issues.

- 1) #3 MED/#3RC/CTO
- 2) East Pfaudler/HC-11 Dryer/#6 RC
- 3) #4 Tunnel Kiln/Mill
- 4) #1 Line/#1RC
- 5) Harrop Kiln
- 6) Horne Tabletting
- 7) #5 RC
- 8) #4RC
- 9) South PK
- 10) #4 RC
- 11) Reduction Towers
- 12) Reduction Tower Screeners
- 13) South Precip

Al-3915 and Al-3920 are starting to move up the list, we are projecting to be late to our commitment to Seneca in delivering the AL-3920 by year end.

In reviewing their plan, we can be ~1 week late at most before it affects them, which in turn affects when the material returns for reduction, which places the burden on us to still meet the QVAM ship date.

Projected end date on the AI-3920 T is showing as Jan 5th.

## **Maintenance & Other**

- 1) #2 Line will be down until Monday at least for spiral repairs #2RC test out new syntron controls while line is down DONE
- 2) Acid wash new pfaudler for repairs week of December 15 DONE
- 3) Vacuum national drier best as possible to soda blast next week Done
- 4) Drop tower 6 bottom and sheave change Monday December 8. Reinstalled
- 5) Need to clean and acid wash T4 and T-6 in Building 27 for checks. timing TBD based on how much 6081 we need to finish and when. Val also needs a week for punchlist items

# **Shipments to finish for December**

- 1) D5253 wraps up this weekend, analyze and ship ASAP
- 2) D-0756 finishes mid December need a plan to ship without final metals analysis ( TDR with ART?)
- 3) V-2046 told Tim C we would target a min of 25K week of Dec 22 with the last week of the month as a fallback, which I would like to avoid.
- 4) Cu-0860 drum fix DONE